



TotalRepair

Guaranteed Repair Solution

Advanced research and development techniques enable Innovatus Imaging to offer TotalRepair – a 100% guaranteed repair solution on select ultrasound probes.

WITH TOTALREPAIR

- Even “totaled” probes can be repaired to avoid costly exchanges and replacements
- You receive the exceptional Innovatus Imaging quality and customer care you expect

TOTALREPAIR OFFERING

- **Guaranteed Repair**
Repair guaranteed on any TotalRepair probe or it is replaced at the repair price
- **Extended Warranty**
TotalRepair services backed by an extended six-month warranty on standard probes
- **Ensured Quality**
Quality systems are ISO-13485:2003 certified

TOTALREPAIR SWAP

Swap your defective probe for a tested replacement at the quoted repair price

- **Speed**
Replacement shipped for next-day delivery
- **Simplicity**
Single transaction reduces shipping and handling
- **Decreased Risk**
Extended six-month warranty covers the entire probe, not just the repair, and no loaner to keep track of or damage

Guaranteed 100% repair solutions on 140 probe models!

TotalRepair – *Guaranteed Repair Solution*

Is your probe missing from the TotalRepair List?

- Innovatus has repair or replacement solutions for over 1100 different probe models including those for Sonosite, GE Voluson E9 and Philips X series.

TotalRepair Guaranteed Probe Models include:

▲ 3D/4D Probe ■ TEE Probe

<p>GE Vivid™/LOGIQ®/E-Series</p> <p>M3S M4S M12L 3.5C 3S 3S-RS 4C 4C-D 4C-RS 4DE7C 4S 5S 6S 6S-D 6S-RS 6T ■ 6T-RS ■ 6T-OR ■ 6Tc ■ 6Tc-RS ■ 7L 7S 9L 9L-D 10L 10S 10S-RS 12L IC5-9-D IC5-9H</p>	<p>GE Voluson</p> <p>AC2-5 RAB2-5 ▲ RAB4-8P ▲ RAB4-8-RS ▲ RAB4-8-D ▲ RAB4-8L ▲ RIC5-9 ▲ RIC5-9-D ▲ RIC5-9H ▲ RIC5-9-RS ▲ RIC5-9W ▲ RIC5-9W-RS ▲ 4C-A</p> <p>GE Venue</p> <p>3S-SC 4C-SC</p> <p>Toshiba</p> <p>PLT-1204AT PST-30BT PST-65AT PVT-661VT</p>	<p>Siemens ACUSON Sequoia™/S2000™</p> <p>EC9-4 EV-8C4 EVC8 L7 TE-V5M ■ TE-V5MS ■ 3V2c 4C1 4V1 4V1c 4V2 5V2c 6C2 6L3 7V3c 8C4 8V3c 8V5 10V4 13L5 15L8 15L8W 17L5HD</p> <p>Siemens ACUSON Antares™</p> <p>CH4-1 CH5-2 CH6-2 EC9-4 PH4-1</p>	<p>Siemens ACUSON Cypress™</p> <p>3V2c</p> <p>Siemens ACUSON</p> <p>L5 L7 V4 4V2c</p> <p>Samsung Medison</p> <p>C2-6IC SVAW 4-7 ▲ SVAW 3-5 ▲ 3D3-5EK ▲ 3D4-7EK ▲</p> <p>Phillips IU22/IE33</p> <p>C5-1 C5-2 C8-4V L8-4 L9-3 L12-5 L15-7io L17-5 S4-1 S5-1 S8-3 S12-4</p> <p>Phillips SONOS</p> <p>S3 S4 11-3L</p>	<p>Philips Envisor/HD Series</p> <p>C5-2 C8-4v L12-3 PA4-2 S3-1 S4 S5-2 S8 S12</p> <p>Philips ATL HDI®</p> <p>C4-2 C5-2 C5-2 ERGO C8-4v L7-4 L12-5 38MM L12-5 50MM P4-1 P4-2</p> <p>Philips CX50/EPIQ</p> <p>C5-2 S5-1 S8-3 S12-4</p>	<p>Limited Supply Models:</p> <p>GE Vivid™/LOGIQ®/E-Series</p> <p>3C-RS 9L-RS 12L-RS</p> <p>Philips IU22/IE33</p> <p>C9-5EC</p> <p>Philips ATL HDI®</p> <p>C9-5 L10-5</p> <p>Siemens ACUSON Sequoia™/ S2000™</p> <p>8L5</p> <p>Siemens ACUSON Antares™</p> <p>PX4-1 VF7-3 VF10-5 VF13-5</p> <p>Toshiba</p> <p>PLT-604AT PLT-704AT PLT-805AT PLT-375AT PLT-375BT</p> <p>Details:</p> <p>May experience extended lead time due to limited parts availability</p>
---	---	---	--	--	--



INNOVATUS IMAGING
575 Epsilon Drive • Pittsburgh, PA 15238
www.innovatusimaging.com

CUSTOMER CARE/ORDERS
1-844-687-5100
customer care@innovatusimaging.com